# Using Siemens NX 11 Software

# Surface Design - Hat

Using surfaces draw the following object from its 2D projections.



**Advice:** the following commands may be useful for constructing the part:

- *Stop at Intersection* .

- *Through Curve Mesh* .

- *Pattern Feature* .

- *Sheet* option in the *Extrude* dialog box .

- *Revolve* .

---